


GARAPA RAIN SCREEN WEATHERING EVALUATION

Penetrating Oil

A mock-up was constructed to evaluate finish weathering performance to establish maintenance requirements.

The following photographs show a Garapa rain screen pre-finished with one coat of penetrating oil (clear).

Location: Wisconsin



Day 1



Day 360

It was determined that an annual reapplication of oil would be required as part of a maintenance program.